

Spa-Francorchamps Round (BEL) from 19th to 21st September 2019

From

The Stewards of the Meeting

The Competitor's Representative Car n° 2 NIELSEN RACING

Decision N° 10

To The Comp

The Stewards, having received a report from the Technical Delegate (report n.6) and having considered the following matter, determine that a breach of the regulations has been committed by the competitor named below and impose the penalty referred to.

Car

2

Competitor

NIELSEN RACING

Session

Race

Facts

The Technical Delegate according with the Notification n.2 of the Stewards checked the crash box mounting. The crashbox fixations found on car 2 are not in compliance with the homologation form (10mm instead of 25mm).

Offence

the crashbox fixations screws (M8 25mm) are not in compliance with the homologation form. (article 1.2 2019 Technical Regulations for LMP3)

Reason

The Stewards heard the Competitor, the Manufacturer and the Technical Delegate. The Competitor recognized that the screws were modified by the Team. The Competitor admitted that this change was done for a quicker change of the crashbox. The delegates remind the stewards that the crashbox is a safety item that is strictly homologated and tested with its fixations. Any modification to this item can produce unforeseen safety problems.

Penalty

Disqualification from Race results.

Article 12.1h) of 2019 Michelin LM Cup Sporting Regulations

Therefore the next Competitors are moved up in the Classification.

The Competitor is reminded of his right of appeal under and in compliance with Art.4.10.2 b) of the Michelin LM Cup Sporting Regulations and Art.15 of the International Sporting Code.

Jordi Parro Chairman Rui Marques

Loïc Bacquelaine ASN Steward

Date

21 September 2019

Time

22h10

Received by the Competitor,

(Signature)

Time 22.44.

Date 21 9 19 -

Copy to: The Competitor

The MLMC Race Director The Clerk of the Course The Secretary of the Meeting

The Press Delegate The Timekeepers

The Official Notice Board

POSTED at: 11 h 49 m